



Pressure Vs Torque Conversion Chart				
<i>Titan T50 Square Drive Tool</i>				
Pressure	<i>Torque</i>		Pressure	<i>Torque</i>
Psi	<i>Ft-Lb</i>		Bar	<i>Kgm Nm</i>
1500	8274		103	1142 11220
1600	8826		110	1218 11968
1800	9929		124	1370 13463
2000	10888		138	1503 14764
2200	11977		152	1653 16241
2400	13066		166	1803 17717
2600	14154		179	1953 19193
2800	15243		193	2104 20670
3000	16299		207	2249 22101
3200	17386		221	2399 23575
3400	18472		235	2549 25048
3600	19559		248	2699 26522
3800	20645		262	2849 27995
4000	21710		276	2996 29439
4200	22796		290	3146 30911
4400	23881		304	3296 32383
4600	24967		317	3445 33855
4800	26052		331	3595 35327
5000	27121		345	3743 36776
5200	28206		359	3892 38247
5400	29291		373	4042 39718
5600	30376		386	4192 41189
5800	31460		400	4342 42660
6000	32532		414	4489 44113
6200	33616		428	4639 45584
6400	34701		442	4789 47054
6600	35785		455	4938 48525
6800	36870		469	5088 49995
7000	37943		483	5236 51451
7200	39027		497	5386 52921
7400	40111		511	5535 54391
7600	41195		524	5685 55861
7800	42279		538	5835 57331
8000	43354		552	5983 58788
8200	44438		566	6132 60258
8400	45522		580	6282 61727
8600	46606		593	6432 63197
8800	47689		607	6581 64667
9000	48765		621	6730 66125
9200	49849		635	6879 67595
9400	50932		649	7029 69064
9600	52016		662	7178 70534
9800	53100		676	7328 72003
10000	54176		690	7476 73463